

***TULLY CENTRAL SCHOOL DISTRICT 2018 FIRE INSPECTION***

**6F-1 Storage in storerooms and classroom areas is orderly and restricted to items of obvious value and usefulness**

Storage room 185 off gym needs to be cleaned up. Have to keep a path to elevator machine room clear

Data room/Lee's storage needs to be cleaned up

**12H-1 Electrical room doors and all disconnects are identified**

Breakers in panel 9-L in Lee's storage room and cafeteria serving line need to be identified

**2D-1 Emergency rescue windows are free of obstructing bars, screens, grilles or classroom equipment**

Room 104 has desk in front of Rescue Window

**15A-2 Furnishings do not obstruct or obscure exits**

Too much paper on door blocking vision panels room 207

**14A-2 Fire resistance rating of rated construction is maintained**

Holes drilled in floor by serving line near electrical panels need to be filed in.

**10A-2 Fire safety and evacuation plans are prepared, maintained and available for review**

Lee's room needs evacuation plans

**17H-2 Means of egress are provided with emergency lighting**

Emergency light/exit signs #35, #13 in auditorium and from library/principals office doesn't function

This building does have to be reinspected

**Bus Storage @ HS (inspected 10/25/18)**

**14C-2 Doors requiring closers are not rendered inoperable by removal of the closer or the installation of any non-automatic hold open devices.**

Flammable storage room door blocked open

This building does not have to be reinspected

**Storage Building, Garage Shop Building, Greenhouse (inspected 10/25/18)**

No non-conformances found at the time of the inspection

**TULLY CENTRAL SCHOOL DISTRICT 2018 FIRE INSPECTION**

**Main Elementary School Building (Inspected 10/25/18)**

**17B-2 Exterior exits are free from obstruction, including snow and ice**

Exit way from gym has chair in it  
Auditorium exit blocked by chairs and dry erase board

**15D-2 Curtains, drapes, hangings and other decorative materials suspended from walls and ceiling shall comply with section 807.4**

Rooms 40, 11 & 43 has pumpkin decorations on the rescue window  
Rooms 25 & 33 has paper leaves on the Rescue Window

**12E-1 No electrical system hazards observed or reported**

Room 43 has a power strip with an extension cord plugged into it  
Room 25 has multi plug adapter on the outlet

**16A-2 Fire detection, alarm and extinguishing systems are operative and inspection, testing and maintenance records are maintained and available for review on premises**

Fire alarm system is in trouble

**12G-1 Electrical service and branch equipment working space is unobstructed**

Room 11 has book case in front of panel box

**3B-1 Certificates are posted that indicate that each boiler has been inspected in compliance with Section 204 of the Labor Law**

No certificate for the boiler

**2D-1 Emergency rescue windows are free of obstructing bars, screens, grilles or classroom equipment**

Rooms 65, 11, 5, 28, has items blocking access to rescue window

**17H-2 Means of egress are provided with emergency lighting**

Emergency light # 74 doesn't work

This building does have to be reinspected.

**Junior Senior High School (inspected 10/25/18)**

**16A-2 Fire detection, alarm and extinguishing systems are operative and inspection, testing and maintenance records are maintained and available for review on premises**

Fire panel in trouble